

# FACILITY COMPLIANCE INSPECTION REPORT

# Division of Waste Management Solid Waste Section

<b>UNIT</b>	UNIT TYPE:													
Lined MSWLF		LCID Notification	X	YW		Transfer		Compost		SLAS		COUNTY: Carteret		
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		NOTIFICATION NO.: N0096		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE		

# **FACILITY NAME AND ADDRESS:**

Willis Construction & Grading Company LCID Landfill 500 Miller Farm Road Morehead City, NC 28557

**GPS COORDINATES**: N: 34.74711 E: 76.79491

### **FACILITY CONTACT NAME AND PHONE NUMBER:**

Billy Miller 252.726.9429

### **FACILITY CONTACT ADDRESS:**

Miller Construction & Landscaping 205 Miller Farm Road Morehead City, NC 28557

E-mail: <u>kathleentaylor217@gmail.com</u>

# **PARTICIPANTS**:

Ray Williams; NCDENR-Solid Waste

# **STATUS OF PERMIT:**

Active: Landclearing and Inert Debris (LCID) Landfill Notification

#### **PURPOSE OF SITE VISIT:**

Comprehensive Facility Compliance Inspection

#### STATUS OF PAST NOTED VIOLATIONS:

None applicable

# **OBSERVED VIOLATIONS:**

None

### **ADDITIONAL COMMENTS:**

- 1) This facility is a Land-Clearing and Inert Debris Landfill Notification under two acres in size.
- 2) This facility is permitted to receive for disposal:
  - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
  - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
  - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
  - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 3) This facility is monitored by a 24 hour security camera at the facility entrance.
- 4) This facility is secured by a locked gate at the facility entrance and has controlled access for safety.
- 5) Proper signage is posted at the facility entrance stating the facility emergency contact number and types of waste accepted.
- 6) The access road to the facility is being managed properly at this time.
- 7) The waste type being disposed is LCID waste only; no unacceptable waste streams were noted during this Facility Compliance Inspection.
- 8) The working face needs to be compacted and maintained in a better defined area. \*Please compact all waste as densely as practical and maintain the working face in as compact an area as is feasible.

#### FACILITY COMPLIANCE INSPECTION REPORT

# Division of Waste Management Solid Waste Section

N0096-20120822INSP

Page 2 of 2

- 9) \*Please ensure that all waste is covered monthly or when the active working faces reaches 1 acre in size, whichever occurs first.
- 10) The perimeter of the landfill has not been staked to identify the landfill footprint. \*Please erect markers delineating the landfill waste footprint boundaries and all required buffers as listed in 15A NCAC 13B .0564 (9) on your LCID notification form.
- 11) Digital photographs were taken during this Facility Compliance Inspection.
- 12) \*Corrective actions are needed as a result of this Audit.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Pay William

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

# Regional Representative

Delivered on: 31 August 2012 by X		Electronic delivery		US Mail		Certified No. [_]
-----------------------------------	--	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: <u>dennis.shackelford@ncdenr.gov</u>
Jessica Montie; Chief Compliance Officer/SWS: <u>jessica.montie@ncdenr.gov</u>

C: \2012\Carteret\Notifications\N0096\Audits\N0096-20120822INSP NCDENR CARA Portal: https://edm.nc.gov/DENR-Portal/